

MS1-1725US
Eugene Luskin
Andrew Petrochuk
David Kizhnerman




Fig. 1

MS1-1725US
Eugene Luskin
Andrew Petrochuk
David Kizhnerman







FIG. 2



MS1-1725US
Eugene Luskin
Andrew Petrochuk
David Kizhnerman



MS1-1725US
Eugene Luskin
Andrew Petrochuk
David Kizhnerman



79G. 5

MS1-1725US
Eugene Luskin
Andrew Petrochuk
David Kizhnerman

602 →

Vehicle Diagnostics Code Explanation

600 →


P0530

The problem could be caused by defects in refrigerant compressor. The approximate cost is:


606 {
\$450 for parts
\$200 for labor
610 }


604 →

608 →



79G. 6





MS1-1725US
Eugene Luskin
Andrew Petrochuk
David Kizhnerman

